

AMENDMENTS TO THE SPECIFICATION

Please replace paragraph bridging pages 25 and 26 with the following rewritten paragraph:

FIG.41A is a longitudinal sectional view showing a reduction gear that contains the assembling error of the hourglass worm, to which the tooth thickness adjusting process is applied, in the axial direction (- direction), and FIG.~~41~~4134B is an enlarged view of an engaging portion.